



## Senkkopfschrauben innensechskant DIN 7991

Festigkeitsklasse 8.8 verzinkt

<b>M4</b> x 10	Best. Nr.	<b>SKS 410</b>
x 12		<b>SKS 412</b>
x 14		<b>SKS 414</b>
x 16		<b>SKS 416</b>
x 18		<b>SKS 418</b>
x 20		<b>SKS 420</b>
x 25		<b>SKS 425</b>
x 30		<b>SKS 430</b>
x 35		<b>SKS 435</b>
x 40		<b>SKS 440</b>

<b>M5</b> x 6	Best. Nr.	<b>SKS 506</b>
x 8		<b>SKS 508</b>
x 10		<b>SKS 510</b>
x 12		<b>SKS 512</b>
x 14		<b>SKS 514</b>
x 16		<b>SKS 516</b>
x 18		<b>SKS 518</b>
x 20		<b>SKS 520</b>
x 25		<b>SKS 525</b>
x 30		<b>SKS 530</b>
x 35		<b>SKS 535</b>
x 40		<b>SKS 540</b>

<b>M6</b> x 8	Best. Nr.	<b>SKS 608</b>
x 10		<b>SKS 610</b>
x 12		<b>SKS 612</b>
x 14		<b>SKS 614</b>
x 16		<b>SKS 616</b>
x 18		<b>SKS 618</b>
x 20		<b>SKS 620</b>
x 25		<b>SKS 625</b>
x 30		<b>SKS 630</b>
x 35		<b>SKS 635</b>
x 40		<b>SKS 640</b>
x 45		<b>SKS 645</b>
x 50		<b>SKS 650</b>

<b>M8</b> x 10	Best. Nr.	<b>SKS 810</b>
x 12		<b>SKS 812</b>
x 14		<b>SKS 814</b>
x 16		<b>SKS 816</b>
x 18		<b>SKS 818</b>
x 20		<b>SKS 820</b>
x 25		<b>SKS 825</b>
x 30		<b>SKS 830</b>
x 35		<b>SKS 835</b>
x 40		<b>SKS 840</b>
x 45		<b>SKS 845</b>
x 50		<b>SKS 850</b>

### *Edelstahl*

<b>M4</b> x 10	Best. Nr.	<b>SKS 410-E</b>
x 12		<b>SKS 412-E</b>
x 14		<b>SKS 414-E</b>
x 16		<b>SKS 416-E</b>
x 18		<b>SKS 418-E</b>
x 20		<b>SKS 420-E</b>
x 25		<b>SKS 425-E</b>
x 30		<b>SKS 430-E</b>
x 35		<b>SKS 435-E</b>
x 40		<b>SKS 440-E</b>

<b>M5</b> x 6	Best. Nr.	<b>SKS 506-E</b>
x 8		<b>SKS 508-E</b>
x 10		<b>SKS 510-E</b>
x 12		<b>SKS 512-E</b>
x 14		<b>SKS 514-E</b>
x 16		<b>SKS 516-E</b>
x 18		<b>SKS 518-E</b>
x 20		<b>SKS 520-E</b>
x 25		<b>SKS 525-E</b>
x 30		<b>SKS 530-E</b>
x 35		<b>SKS 535-E</b>
x 40		<b>SKS 540-E</b>

<b>M6</b> x 8	Best. Nr.	<b>SKS 608-E</b>
x 10		<b>SKS 610-E</b>
x 12		<b>SKS 612-E</b>
x 14		<b>SKS 614-E</b>
x 16		<b>SKS 616-E</b>
x 18		<b>SKS 618-E</b>
x 20		<b>SKS 620-E</b>
x 25		<b>SKS 625-E</b>
x 30		<b>SKS 630-E</b>
x 35		<b>SKS 635-E</b>
x 40		<b>SKS 640-E</b>
x 45		<b>SKS 645-E</b>
x 50		<b>SKS 650-E</b>

<b>M8</b> x 10	Best. Nr.	<b>SKS 810-E</b>
x 12		<b>SKS 812-E</b>
x 14		<b>SKS 814-E</b>
x 16		<b>SKS 816-E</b>
x 18		<b>SKS 818-E</b>
x 20		<b>SKS 820-E</b>
x 25		<b>SKS 825-E</b>
x 30		<b>SKS 830-E</b>
x 35		<b>SKS 835-E</b>
x 40		<b>SKS 840-E</b>
x 45		<b>SKS 845-E</b>
x 50		<b>SKS 850-E</b>